

CHRYSLER B1638: RIGHT HIGH BEAM CONTROL CIRCUIT HIGH

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$50-\$400
Can I Still Drive?	:	Yes

What Does The Chrysler B1638 Code Mean?

When the Totally Integrated Power Module (TIPM) detects a high condition.

What Are The Potential Causes Of The Chrysler B1638 Code?

- (L34) RIGHT HIGH BEAM CONTROL CIRCUIT OPEN
- (L34) RIGHT HIGH BEAM CONTROL CIRCUIT SHORTED TO VOLTAGE
- (L910) HEADLAMP RETURN SIGNAL CIRCUIT OPEN
- RIGHT HIGH BEAM BULB
- TOTALLY INTEGRATED POWER MODULE (TIPM)

Reference Sources

[Chrysler B1638](#), DTCDECODE.