

CHRYSLER B1852: DRIVER WINDOW SWITCH STUCK

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$200-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Chrysler B1852 Code Mean?

When the (D506) LIN Bus circuit at the Window Switch is held in the Driver Window value for over 10 seconds, this code will set.

What Are The Potential Causes Of The Chrysler B1852 Code?

- (D506) LIN bus circuit partial short to ground
- Window switch stuck
- Instrument cluster

Reference Sources

[Chrysler B1852](#), DTCDECODE.