

## CHRYSLER B1956: POWER LIFTGATE LATCH RELEASE - EXCESSIVE TIME

### OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$100-\$500
Can I Still Drive?	:	<b>Yes</b> (Short-term only)

### What Does The Chrysler B1956 Code Mean?

The latch motor should perform its operation within 4 seconds. When it takes longer for the release operation, this code will set.

### What Are The Potential Causes Of The Chrysler B1956 Code?

- Binding liftgate
- Low battery voltage
- Latch not in home position
- Liftgate latch cinch driver circuit faulty wiring
- Liftgate latch release driver circuit faulty wiring
- Liftgate switch sense circuit faulty wiring
- Logic ground circuit faulty wiring
- Latch assembly

### Reference Sources

[Chrysler B1956](#), DTCDECODE.