

CHRYSLER B1B18: LEFT SIDE CURTAIN SQUIB 1 CIRCUIT LOW

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$80-\$800
Can I Still Drive?	:	Yes

What Does The Chrysler B1B18 Code Mean?

With the ignition on. The Occupant Restraint Controller (ORC) monitors the resistance of the Left Seat Squib circuits. The ORC will set this DTC if it detects low resistance of the Airbag Seat Left Thorax Squib 1 circuits

What Are The Potential Causes Of The Chrysler B1B18 Code?

- (R3) LEFT SEAT SQUIB 1 LINE 1 CIRCUIT SHORTED TO GROUND
- (R1) LEFT SEAT SQUIB 1 LINE 2 CIRCUIT SHORTED TO GROUND
- LEFT SEAT AIRBAG
- OCCUPANT RESTRAINT CONTROLLER (ORC)

Reference Sources

[Chrysler B1B18](#), DTCDECODE.