

CHRYSLER B1B19: LEFT SIDE CURTAIN SQUIB 1 CIRCUIT HIGH

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$80-\$800
Can I Still Drive?	:	Yes

What Does The Chrysler B1B19 Code Mean?

The Occupant Restraint Controller (ORC) monitors the voltage on the Left Seat Squib 1 circuits. The ORC will set this DTC if it detects voltage on the Left Seat Squib 1 circuits.

What Are The Potential Causes Of The Chrysler B1B19 Code?

- (R3) left seat squib 1 line 1 circuit shorted to battery
- (R1) left seat squib 1 line 2 circuit shorted to battery
- Left seat airbag
- Occupant restraint controller (ORC)

Reference Sources

[Chrysler B1B19](#), DTCDECODE.