INITIALIZED		
		OVERVIEW
Severity	:	Hig
DIY Difficulty Level	:	Advance
Repair Cost	:	\$150-\$500

What Does The Chrysler C121A Code Mean?

The Steering Angle Sensor (SAS) has set an internal failure status.

What Are The Potential Causes Of The Chrysler C121A Code?

Clockspring/Sas

Reference Sources

<u>Chrysler C121A</u>, DTCDECODE.

