

HONDA B1229: OPEN IN THE SUNLIGHT SENSOR CIRCUIT

OVERVIEW

Severity	:	Medium
DIY Difficulty Level	:	Intermediate
Repair Cost	:	\$100-\$350
Can I Still Drive?	:	Yes (Short-term only)

What Does The Honda B1229 Code Mean?

Poor communication between the Sunlight Sensor and the Climate Control Unit. ("Open") condition.

What Are The Potential Causes Of The Honda B1229 Code?

- Perform the HVAC self-diagnostic function with the HDS
- ("Open") in the wires between the Climate Control Unit and the Sunlight Sensor
- Faulty Sunlight Sensor
- Faulty Climate Control Unit

Reference Sources

[Body Electrical Repair Information for B1229](#) - American Honda Motor, page 88.