

HONDA B1843: UART COMMUNICATION ERROR

OVERVIEW

Severity	:	<div><div>Medium</div></div>
DIY Difficulty Level	:	<div><div>Intermediate</div></div>
Repair Cost	:	\$75-\$300
Can I Still Drive?	:	Yes (Short-term only)

What Does The Honda B1843 Code Mean?

NOTE: If you are troubleshooting multiple DTCs, be sure to follow the instructions in B-CAN System Diagnosis Test Mode A.

What Are The Potential Causes Of The Honda B1843 Code?

- Fuse
- Open in the UART wire between the power mirror control unit and power seat control unit
- Open or high resistance in the wire between the power mirror control unit and body ground
- Faulty power mirror control unit

Reference Sources

[Honda B1843](#), DTCDECODE.