MAZDA B2868: WHEEL UNIT NO.1 INTERNAL MALFUNCTION

OVERVIEW

Severity : Medium

DIY Difficulty Level : Intermediate

Repair Cost : \$50-\$500

Can I Still Drive? : Yes (Short-term only)

What Does The Mazda B2868 Code Mean?

The instrument cluster receives error signals from the wheel unit.

What Are The Potential Causes Of The Mazda B2868 Code?

Internal malfunction of wheel unit

Reference Sources

Mazda B2868, DTCDECODE.

