

What Does The Nissan C1130 Code Mean?

Based on the signal from ECM, ABS actuator and electric unit (control unit) judges that engine fuel cut system is malfunctioning.

What Are The Potential Causes Of The Nissan C1130 Code?

- Harness or connector
- ABS actuator and electric unit (control unit)
- ECM
- CAN communication line

How Can You Fix The Nissan C1130 Code?

Perform an ECM self-diagnosis and repair or replace malfunctioning items.

Reference Sources

BRAKE CONTROL SYSTEM SERVICE MANUAL for C1130 - Page 42.

