

NISSAN C1181: ABS ACTIVE BOOSTER

OVERVIEW

Severity	:	<div></div> High
DIY Difficulty Level	:	<div></div> Advanced
Repair Cost	:	\$300-\$1300
Can I Still Drive?	:	No

What Does The Nissan C1181 Code Mean?

Active booster response is malfunctioning, or signal line of active booster response is open or shorted.

What Are The Potential Causes Of The Nissan C1181 Code?

- Harness or connector
- Active booster
- ABS actuator and electric unit
- (control unit)

Reference Sources

[BRAKE CONTROL SYSTEM SERVICE MANUAL for C1181](#) - Pages 72-74.