NISSAN C1189: ABS ACTIVE BOOSTERE		
	C	OVERVIEW
Severity	:	Higi
severity	•	' ''8'
DIY Difficulty Level	:	Advance
Repair Cost	:	\$300-\$1300
Can I Still Drive?	:	No

What Does The Nissan C1189 Code Mean?

Brake booster is defective or malfunctioning.

What Are The Potential Causes Of The Nissan C1189 Code?

- Harness or connector
- Active booster
- ABS actuator and electric unit (control unit)

Reference Sources

BRAKE CONTROL SYSTEM SERVICE MANUAL for C1189 - Pages 72-74.

