

NISSAN C16A1: EPS DC/DC CONVERTER

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$300-\$600
Can I Still Drive?	:	Yes (Short-term only)

What Does The Nissan C16A1 Code Mean?

Malfunction has been detected from EPS DC/DC converter.

What Are The Potential Causes Of The Nissan C16A1 Code?

- EPS DC/DC converter
- HV ECU
- Harness or connector
- EPS control unit

Reference Sources

[STEERING CONTROL SYSTEM SERVICE MANUAL for C16A1](#) - 2008 Altima Hybrid, pages 33-36.