

SUBARU P1703: LOW CLUTCH TIMING CONTROL SOLENOID VALVE CIRCUIT MALFUNCTION

OVERVIEW

Severity	:	High
DIY Difficulty Level	:	Advanced
Repair Cost	:	\$60-\$420
Can I Still Drive?	:	Yes

What Does The Subaru P1703 Code Mean?

Engine started, vehicle driven to a speed of over 3 mph, and the PCM detected an unexpected voltage condition on the A/T Low Clutch Timing Control Solenoid circuit during the CCM test.

How Can You Fix The Subaru P1703 Code?

Check low clutch timing control solenoid valve circuit

Reference Sources

[Subaru Impreza Repair Manual for P1703](#) - Page 667.